

# City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form

Page 1 of 6

Sewershed : Gwynn Falls

Company : URS

Date : 12/02/2008

Test to be Performed :  
Smoke : X Dyed Water :   

Ground Condition :  
Dry :    Damp : X Wet :   

Supervisor : John Daly

Manhole ID : S01AA1013MH

Test ID : S1032-026012

Notifications (Residents, Fire, 311) :  
Yes

**Field Sketch :** (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)



LEGEND		Defect Code	Defect Description	Defect Code	Defect Description
N ↑	⊗	SL	Service Lateral	CB	Catch Basin
	●	TJ	Transition Joint	SD	Storm Ditch
	●	DD	Driveway Drain	SWMH	Storm Manhole
	→	WWD	Window Well Drain	MAIN	Main Sewer
	—	STRD	Stairwell Drain	SANMH	Sewer Manhole
	—	AD	Area Drain	CO	Cleanout
	—	DS	Downspout	OTHER	Other
	—	DSC	Downspout Connection	IOB	Inside of Building
	—	FD	Foundation Drain		
	—				

City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form		Page 2 of 6
Sewershed : <u>Gwynn Falls</u>	Company : <u>URS</u>	Date : <u>12/02/2008</u>
Test to be Performed : Smoke : <u>X</u> Dyed Water : <u>  </u>	Ground Condition : Dry : <u>  </u> Damp : <u>X</u> Wet : <u>  </u>	Supervisor : <u>John Daly</u>
Manhole ID : <u>S01AA1013MH</u>	Test ID : <u>S1032-026012</u>	Notifications (Residents, Fire, 311) : <u>Yes</u>
Field Sketch : (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)		
<div> <div> <div>ID</div> <div>  </div> <div> Location: N/A; Type: Service Lateral; Smoke: Heavy; Status: Private Property </div> <div>Landscape</div> <div>  </div> <div>Defect</div> <div>  </div> </div> <div> <div>ID</div> <div>  </div> <div> Location: N/A; Type: Service Lateral; Smoke: Light; Status: Private Property </div> <div>Landscape</div> <div>  </div> <div>Defect</div> <div>  </div> </div> </div>		



# City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form

Page 3 of 6

Sewershed : Gwynn Falls

Company : URS

Date : 12/02/2008

Test to be Performed :  
Smoke : X Dyed Water :   

Ground Condition :  
Dry :    Damp : X Wet :   

Supervisor : John Daly


Manhole ID : S01AA1013MH

Test ID : S1032-026012

Notifications (Residents, Fire, 311) :  
Yes

**Field Sketch :** (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)

ID



Location: N/A; Type: Main Sewer; Smoke: Medium; Status: Private Property


Landscape



Defect



ID



Location: N/A; Type: Catch Basin; Smoke: Heavy; Status: Public ROW

Landscape



Defect





# City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form

Page 4 of 6

Sewershed : Gwynn Falls

Company : URS

Date : 12/02/2008

Test to be Performed :  
Smoke : X Dyed Water :   

Ground Condition :  
Dry :    Damp : X Wet :   

Supervisor : John Daly


Manhole ID : S01AA1013MH

Test ID : S1032-026012

Notifications (Residents, Fire, 311) :  
Yes

**Field Sketch :** (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)

ID



Location: N/A; Type: Catch Basin; Smoke: Medium; Status: Public ROW


Landscape



Defect



ID



Location: N/A; Type: Main Sewer; Smoke: Medium; Status: Public ROW

Landscape



Defect



# City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form

Page 5 of 6

Sewershed : Gwynn Falls

Company : URS

Date : 12/02/2008

Test to be Performed :  
Smoke : X Dyed Water :   

Ground Condition :  
Dry :    Damp : X Wet :   

Supervisor : John Daly


Manhole ID : S01AA1013MH

Test ID : S1032-026012

Notifications (Residents, Fire, 311) :  
Yes

**Field Sketch :** (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)

ID



Location: N/A; Type: Main Sewer; Smoke: Light; Status: Public ROW


Landscape



Defect



ID



Location: N/A; Type: Cleanout; Smoke: Light; Status: Public ROW




Landscape



Defect





City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form		Page 6 of 6
Sewershed : <u>Gwynn Falls</u>	Company : <u>URS</u>	Date : <u>12/02/2008</u>
Test to be Performed : Smoke : <u>X</u> Dyed Water : <u>  </u>	Ground Condition : Dry : <u>  </u> Damp : <u>X</u> Wet : <u>  </u>	Supervisor : <u>John Daly</u>
Manhole ID : <u>S01AA1013MH</u>	Test ID : <u>S1032-026012</u>	Notifications (Residents, Fire, 311) : <u>Yes</u>
Field Sketch : (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)		
<div> <div>ID</div> <div>  <p>Location: N/A; Type: Area Drain; Smoke: Light; Status: Private Property</p> </div> <div>Landscape</div> <div>  </div> <div>Defect</div> <div>  </div> </div>		